ADSL2/2+ Router

Upgrade Firmware via Web

Reset to Default Setting

- Reset to default setting first

Upgrade Firmware

- Upgrade Firmware via web page
- Select Firmware, file name should be "**nsp.annexA.firmware.upgrade.img**" or "**nsp.annexB.firmware.upgrade.img**"

Upgrade Firmware

- Upgrading will take about 3~4 mins and show this page
- Ping 192.168.1.1, if the ping get "Request time out" for a while, means upgrading firmware is successful and router is rebooting
- Done !